

Under Review Notification

Raised By: Vanessa Morel

Product #: RBW0905G00134-3G-03

Date: 2019.10.23

Product Name: TOW DOLLY

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank								Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
RBW0905G00134-3G-03	RBW0905G00134-3G-03 Rev 5	Y	Y	N	Y	Y	N	N	N	19-949	See below

Description of Issue:
 Issues stated on ADR (Fit issues, manufacturing issues)
 RBW0905G00134-3G-03 and all sub assy and parts must be put on **HOLD** in Plex (Hardware no need to be in hold)
 RBW0905G00134-3G-03 Finish good stock can be use
 All sub assys and parts must be put in quarantine
 No new manufacturing is permitted until Engineering release new Rev
 Can remain on website with a note to contact sales for a quote. They must **NOT** be able to put the tool into cart
 'P' Part must be put on **HOLD** in Plex as well

Distribution:	VP Operations	Director of Engineering	Customer Support Manager	Technical Support
	Director of Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
	Director Quality Assurance	Engineering Project Managers	Production Planners	Supply Chain Director / Senior Buyer
	QC Coordinator	Engineering Clerk	Purchasing Manager	Marketing Eugene